


**NOTICE TO MARINERS**

**Issue date: 11/02/2022**

**1. Completion of Works**

The works associated with the Offshore Transmission (OfTI) and Offshore Substation Platforms (OSPs) were completed on the 13<sup>th</sup> January 2022. Overall care, custody and control of the works has been handed over to the Moray East Operations and Maintenance Team. Please note, construction works associated with the Windfarm Infrastructure remain ongoing.



Note that the construction demarcation marker buoys are still present at the site as stated in Table 1 below.

**Table 1. Demarcation buoy locations**

Name	WGS84		WGS84 UTM Zone 30N	
	Latitude (dms)	Longitude (dms)	Easting (m)	Northing (m)
<b>Buoy 1 - North Cardinal Buoy,</b> Pillar shaped with a north cardinal shaped top mark, exhibiting a Quick (Q) White (W) light character and AIS.	58° 18' 6.600" N	2° 41' 4.800" W	518481.96	6462358.27
<b>Buoy 2 - Special Mark Buoy,</b> Pillar shaped with a yellow 'x' shaped top mark, exhibiting a Fl Y 5s light character.	58° 16' 48.300" N	2° 37' 55.380" W	521579.08	6459952.33
<b>Buoy 3 - Special Mark Buoy,</b> Pillar shaped with a yellow 'x' shaped top mark, exhibiting a Fl Y 5s light character.	58° 15' 8.460" N	2° 35' 57.300" W	523521.05	6456875.58
<b>Buoy 4 - East Cardinal Buoy,</b> Pillar shaped with an east cardinal shaped top mark, exhibiting a Very (V) Q (3) 5 second (s) W light character	58° 10' 44.10" N	2° 32' 45.85" W	526697.39	6448719.65
<b>Buoy 5 - Special Mark Buoy,</b> Pillar shaped with a yellow 'x' shaped top mark, exhibiting a Fl Y 5s light character.	58° 7' 49.680" N	2° 35' 20.640" W	524201.44	6443309.27

# MORAY EAST OFFSHORE WINDFARM

8460001-PC0010-MWE-NTM-0061




Figure 1 – Demarcation Buoy locations

Name	WGS84		WGS84 UTM Zone 30N	
	Latitude (dms)	Longitude (dms)	Easting (m)	Northing (m)
<b>Buoy 6 - Special Mark Buoy,</b> Pillar shaped with a yellow 'x' shaped top mark, exhibiting a Fl Y 5s light character.	58° 6' 43.980" N	2° 38' 19.860" W	521280.40	6441260.65
<b>Buoy 7 - Special Mark Buoy,</b> Pillar shaped with a yellow 'x' shaped top mark, exhibiting a Fl Y 5s light character.	58° 4' 57.240" N	2° 47' 9.360" W	512624.16	6437922.64
<b>Buoy 8 – South Cardinal,</b> Pillar shaped with a south cardinal shaped top mark, exhibiting a V Q (6) + L Fl 10sW light character and AIS.	58° 4' 1.140" N	2° 52' 6.660" W	507757.35	6436175.21
<b>Buoy 9 - Special Mark Buoy,</b> Pillar shaped with a yellow 'x' shaped top mark, exhibiting a Fl Y 5s light character.	58° 8' 37.080" N	2° 50' 37.080" W	509205.67	6444712.15

## 2. General Safety Advice

Please be aware that while navigating the area to keep an extra look out for the unlit buoy 9 Special mark during the hours of darkness and reduced visibility

## 3. Contact details

The following contact can provide more information if required. Please note that specific queries can also be addressed to the relevant vessel or shore based representative.

<b>CONTACT DETAILS</b>	
<b>Marine Coordination Centre 24/7</b>  Peter Garden – Lead Marine Coordinator  Email peter.garden@oceanwinds.com  Tel : +44 07884630427	<b>For fisheries related matters</b>  Alex Winrow-Giffin – Brown and May Marine Ltd.  Email: alex@brownmay.com  Tel : +44 1379 872148 / +44 7760 160039