

NOTICE TO MARINERS

OSP Radiator Replacement programme

Moray East Offshore Wind Farm

Issue Date	07/07/2026
Version	01
Activity	OSP Radiator replacement on all OSPs

Revision History

Version	Issue Date	Status	Updates
01	07/07/2026	Final	First issue

Radiator Replacement programme

Please be advised that Moray Offshore Windfarm (East) Limited (Moray East) are planning to undertake a Radiator Replacement programme on all 3 Offshore Sub station Platforms (OSPs) using the Jack Up Vessel HEA Hydra presented in Figure 2 below, starting approximately 23.07.2026 for 30 days weather dependant.

The coordinates of the work site boundary are presented in the below Table 1 and shown in **Error! Reference source not found.** The coordinates of the OSPs are presented in Table 2 below and shown in Figure 1.

Table 1: Moray East Site boundary

Coordinates			
Easting	Northing	Latitude	Longitude
515330.83	6464697.91	58° 19.378' N	2° 44.296' W
525198.17	6453175.00	58° 13.141' N	2° 34.265' W
525337.48	6443784.17	58° 08.080' N	2° 34.184' W
505117.13	6436034.64	58° 03.946' N	2° 54.796' W
509820.00	6445320.00	58° 08.945' N	2° 49.990' W
507393.03	6452043.96	58° 12.571' N	2° 52.451' W
512568.09	6458210.62	58° 15.887' N	2° 47.147' W

Table 2: Moray East OSP coordinates

Structure	Coordinates			
	Easting	Northing	Latitude	Longitude
OSP1	513911	6442737	58° 07.550' N	2° 45.830' W
OSP2	515458	6452876	58° 13.010' N	2° 44.210' W
OSP3	520100	6447184	58° 09.930' N	2° 39.500' W




Figure 1: Location of Wind Farm Site

HEA Hydra			
TYPE	Self-Propelled Jack Up Vessel	OPERATOR	Zakher Marine International
IMO	9669093	LOA	76m
MMSI No.	370239000	BEAM	41.2m
CALLSIGN	3FEI3	DRAUGHT	7.0m
FLAG	Panama	DATE ON SITE	23.07.2026
CONTACT TEL	+971506419196 / +97125515151	LICENCES	All Wind Farm
On Board Contact:	Naim Faisal master.heahydra@qms-fleet.com		
Onshore Representative:	Hamid Ur Rehman Email: Hamid.Rehman@zmiglobal.com Tel: +97125515151		



Figure 2: HEA Hydra

Figure 2: HEA Hydra

1. General Safety Advice

Please be aware that, during the survey activities, by virtue of its mode of operation the vessel (HEA Hydra) will be Restricted in her Ability to Manoeuvre (RAM) as defined under COLREGs (International Regulations for Preventing Collisions at Sea 1972, Rule 3). Masters of vessels are therefore requested to maintain their vessels and gears at a minimum safe passing distance from the vessel of 500 metres when it is undertaking work and showing the appropriate shapes and lights in accordance with COLREGs Rule 27.

In order to not compromise the safety of the Survey Vessel, their crew, and their ability to undertake its contracted works, fishermen who have static fishing gears deployed within 500 m from the OSP where maintenance activities are planned (see Table 2 and Figure 1) are requested to provide the coordinates of such deployed gears in DMS and details of whether the surface

8460001-PC0010-MWE-NTM-0112

markers used are visible at all states of visibility to Alex Winrow-Griffin (Brown & May Marine) using the contact information below (Section 58 of the Merchant Shipping Act 1995).

Fishermen who have static gears deployed beyond 12 nm are reminded that static gear must be marked in accordance with Commission Implementing Regulation (EU) No. 404/2011 (<https://www.gov.uk/guidance/markings-of-fishing-gear-retrieval-and-notification-of-lost-gear#marking-of-fishing-gear>)

2. Contact details

CONTACT DETAILS	
Marine Coordination Centre 24/7 Duty Marine Coordinator Email MCC@morayeast.com Tel : +44 07884630427	For fisheries related matters Alex Winrow-Giffin – Brown and May Marine Ltd. Email: alex@brownmay.com Tel : +44 1379 872148 / +44 7760 160039

The following contact can provide more information if required. Please note that specific queries can also be addressed to the relevant vessel or shore-based representative.