

NOTICE TO MARINERS

Issue date: 30/06/2022

1. Met Mast Special mark unlit

Please be advised that Moray East Met Mast Special Mark buoy has been reported as unlit

Further details on the buoy location are provided below


Update on vessel(s) involved in the repair work will be provided through future NtMs These can be accessed in the Moray East website at:

<http://www.morayoffshore.com/moray-east/the-project/notices-to-mariners/>

Table 1. Met Mast Special Mark buoy location

Name	WGS84		WGS84 UTM Zone 30N	
	Latitude (dms)	Longitude (dms)	Easting (m)	Northing (m)
Met Mast Special Mark Buoy , Pillar shaped with a Yellow X shaped top mark, exhibiting a Flashing Yellow light 5s character	58° 10' 928" N	2° 49' 215" W	510574	6449000

Figure 1 – Met Mast location



2. General Safety Advice

Please be aware that while navigating the area to keep an extra look out for the unlit Met Mast Special marker buoy during the hours of darkness and reduced visibility, until such a time as the buoy is repaired.

3. Contact details

CONTACT DETAILS	
<p>Marine Coordination Centre 24/7 Peter Garden – Lead Marine Coordinator Email peter.garden@oceanwinds.com Tel : +44 07884630427</p>	<p>For fisheries related matters Alex Winrow-Giffin – Brown and May Marine Ltd. Email: alex@brownmay.com Tel : +44 1379 872148 / +44 7760 160039</p>