

NOTICE TO MARINERS

Issue date: 17/11/2023

1. Moray East Met Mast Special Mark unlit

Please be advised that Moray Offshore Windfarm (East) Limited (Moray East) special mark buoy has been reported as unlit around the remaining subsea structure at the meteorological mast (Met Mast) (See Figure 1).

Please also note that the Met Mast is currently marked by a virtual AtoN.

Update on vessel(s) involved in the repair work will be provided through future NtMs. These can be accessed in the Moray East website at:

<http://www.morayoffshore.com/moray-east/the-project/notices-to-mariners/>




Figure 1 Moray East Site and Met Mast Location

Table 1 Met Mast Special Mark buoy location

| Name | Coordinates (WGS84) | |
|----------------------------|---------------------|-----------------|
| | Latitude (dms) | Longitude (dms) |
| Met Mast Special Mark Buoy | 58°10'33.360" N | 2°49'07.619" W |

2. General Safety advice

8460001-PC0030-MWE-NTM-0086

Please be aware that while navigating the area to keep an extra look out for the unlit Met Mast Special marker buoy during the hours of darkness and reduced visibility, until such a time as the buoy is repaired.

3. Contact details

The following contact can provide more information if required. Please note that specific queries can also be addressed to the relevant vessel or shore-based representative.

| Contact details | |
|-----------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Marine Coordination Centre 24/7 Email mcc@morayeast.com Tel : +44 07884630427 | For fisheries related matters Alex Winrow-Giffin – Brown and May Marine Ltd.Email: alex@brownmay.com Tel : +44 1379 872148 / +44 7760 160039 |