

NOTICE TO MARINERS

Issue date: 23/02/2024

1. Moray East Met Mast Special Mark unlit - updated

Please be advised that Moray Offshore Windfarm (East) Limited (Moray East) special mark buoy has been reported as unlit around the remaining subsea structure at the meteorological mast (Met Mast) (See Figure 1). Following previous Notice to Mariners, the operations to repair the light at the Met Mast buoy has been aborted due to adverse weather conditions. Another attempt to reinstate the lighting of the buoy will be made at the earliest possibility. It is currently planned for the week of the 18th of March. Another NtM will be issued in due course.

Please also note that the Met Mast is currently marked by a virtual AtoN.

Update on vessel(s) involved in the repair work will be provided through future NtMs. These can be accessed in the Moray East website at:

<http://www.morayoffshore.com/moray-east/the-project/notices-to-mariners/>




Figure 1 Moray East Site and Met Mast Location

Table 1 Met Mast Special Mark buoy location

Name	Coordinates (WGS84)	
	Latitude (dms)	Longitude (dms)
Met Mast Special Mark Buoy	58°10'33.360" N	2°49'07.619" W

2. General Safety advice

Please be aware that while navigating the area to keep an extra look out for the unlit Met Mast Special marker buoy during the hours of darkness and reduced visibility, until such a time as the buoy is repaired.

3. Contact details

The following contact can provide more information if required. Please note that specific queries can also be addressed to the relevant vessel or shore-based representative.

Contact details	
<p>Marine Coordination Centre 24/7 Email mcc@morayeast.com Tel : +44 07884630427</p>	<p>For fisheries related matters Alex Winrow-Giffin – Brown and May Marine Ltd. Email: alex@brownmay.com Tel : +44 1379 872148 / +44 7760 160039</p>