UNIVERSITY OF ABERDEEN

NOTICE TO MARINERS No. UoA/08/2020

MORAY FIRTH, SCOTLAND

Date of notice: 11th August, 2020

Mariners are advised that the University of Aberdeen has <u>**removed**</u> moorings and equipment at the locations listed in table 1. Mariners should also note that the University of Aberdeen has <u>serviced and reinstalled in</u> <u>its existing location</u> the mooring and equipment listed in table 2.

Table 1. Mooring / equipment removed.

Name	Coordinates (WGS84 datum)		Characteristics
IMF-1	57º 40.860' N	003º 59.283' W	Subsurface. Ground line.
IMF-2	57º 41.273' N	003º 58.928' W	Subsurface. Ground line.
IMF-3	57º 40.630' N	003º 56.105' W	Subsurface. Ground line.
IMF-4	57º 39.217' N	004º 01.090' W	Subsurface. Ground line.
IMF-5	57º 38.648' N	003º 57.907' W	Subsurface. Ground line.
IMF-6	57º 37.936' N	004º 02.275' W	Subsurface. Ground line.
IMF-7	57º 36.699' N	004º 04.650' W	Subsurface. Ground line.
IMF-8	57º 36.604' N	004º 01.280' W	Subsurface. Ground line.
IMF-9	57º 36.310' N	003º 57.772' W	Subsurface. Ground line.
IMF-10	57º 34.655' N	004º 04.458' W	Subsurface. Ground line.
IMF-11	57º 34.654' N	004º 05.518' W	Subsurface. Ground line.


Table 2. Mooring / equipment serviced & reinstalled.

Nar	ne	Coordinates (WGS84 datum)		Characteristics
02	2	57º 35.118' N	004º 05.875' W	Surface marked (round buoy). Ground line.

A further Notice to Mariners will be issued in the event of additional operations on the above locations.

For information and enquiries please contact: Tim Candido Barton, Lighthouse Field Station, University of Aberdeen, George St., Cromarty, Ross-shire, IV11 8YL. +44 (0)1381 600548. <u>t.r.barton@abdn.ac.uk</u>






Lander (700 x 500mm)



Sound recorder (200 x 60mm)

Examples of equipment which the above moorings support.



Mooring locations noted in this Notice to Mariners.