

NOTICE TO MARINERS

Issue date: 26/01/2024

1. Exclusion Zone established at H05 on Moray East Wind Farm

Please be advised that Moray Offshore Windfarm (East) Limited (Moray East) has established an exclusion zone of 500m around WTG (Wind Turbine Generator) H05. This is due to a section of fibreglass lifting on the roof of the Nacelle, which has the potential to become a dropped object.

Table 1 : H05 500m Exclusion Zone

WTG ID	Coordinates	
	Latitude (DD MM.mmm)	Longitude (DD MM.mmm)
ME-H05	58° 06.900' N	002° 41.107' W




Figure 1: WTG Location where 500m exclusion zone has been established H05 Circled in Red.

2. General Safety Advice

Advise all vessels to exercise caution when at or near the area of H05 ensuring a safe passing distance, extreme vigilance in case the fibreglass roof is dislodged and becomes a danger to navigation. Moray East Marine Coordination Centre will be monitoring the Moray East Wind Farm via AIS. If any further information is required, please contact via the details below.

3. Contact details

CONTACT DETAILS	
Marine Coordination Centre 24/7 Email mcc@morayeast.com Richard Mutch – Lead Marine Coordinator Email richard.mutch@oceanwinds.com Tel : +44 07884630427	For fisheries related matters Alex Winrow-Giffin – Brown and May Marine Ltd. Email: alex@brownmay.com Tel : +44 1379 872148 / +44 7760 160039

The following contact can provide more information if required. Please note that specific queries can also be addressed to the relevant vessel or shore-based representative.